Form 3860-10 (October 1979) (formerly 3400-11)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

1	Mir	eral	Survey	number
		48		

State

Arizona

FIELD NOTES

Land District Arizona

Of the Survey of the Mining Claim of (name and address of Claimant)

Harborlite Corporation P. O. Box 458 Escondido, CA 92025

Known as the (name of group, if any)

Mining district
Mineral Creek

Township


				DATE		
NAME OF LO	CATION			LOCATED	AMENDE	
Harborlite Millsite No	. 1			10-8-74		
narborrice militate no	• 1			10-0-74		
Harborlite Millsite No	. 2			10-8-74		
			9			
					l	
		9				
54					1	

Range 12 East Section 4 2 South <u>Gila & Salt River</u> Nov. 30, 1981 Survey completed December 15, 1981 Survey commenced Name of Mineral Surveyor December 1, 1981 Harvey W. Smith

County Pinal

Meridian

Survey under order dated



FEET

This survey was made with a Swiss Kern Theodolite, Model DKM 1. No. 77769, having horizontal and vertical circles, 50 mm. in diam. The circles are graduated in degrees and 20-minute increments. An optical micrometer, adjustable to the vertical and horizontal circles, permits the reading of angles direct to ten-second accuracy and estimating to one-second accuracy. instrument was in good condition at the time of the survey and all adjustments were in good order.

All azimuths in this record were determined by the method of horizontal-angles-right referred to the meridian determined by the following observation:

December 10, 1981, at Cor. No. 1 of the Harbor-lite Millsite No. 1, latitude 33°17.3'N., longitude 111°07.4'W., elevation 2,710 ft. above sea level, and temperature 76°F., make a series of six altitude observations on the sun for azimuth at approximately equal time intervals, three each with the telescope in direct and reversed positions, observing opposite limbs of the sun, and reading the horizontal angle from a reference point about 1,800 ft. northeastward to the sun.

Mean time of observation, 105th meridian standard $= 9^{h}40^{m}15^{s}a.m.$

Declination of sun at mean = 22°56'54.6"S. time of observation

Mean observed vertical angle to sun's center = 25°29'23"

Mean horizontal angle from reference point clockwise to sun's center = 109°36'02"

True bearing to reference point = N.36°25'22"E.

The lines were measured with a Lufkin steel tape, 300 ft. in length, graduated every foot for 299 ft. and the remaining foot graduated to tenths and hundredths: the tape was compared to an Invar standard tape at the beginning of the survey and found to be correct. In addition to the steel tape, a K & E Autoranger infrared distance measuring unit was used to measure some of the lines. Its accuracy was checked against a line measured with the foregoing steel tape and found to be correct.

All lines and connections of this survey run by direct methods.

The magnetic declination observed at each corner of the survey gave a uniform value of 13°30'.

Mineral Survey No. 4845

FEET	HARBORLITE MILLSITE NO. 1		
	At Cor. No. 1 of the Harborlite Millsite No. 1.		
	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X H. M.S. 1 1 U.S.M.S. 4845; from which		
	The S. 1/4 sec. cor. of sec. 34, T.1 S., R.12 E., G.& S.R.M., bears N.36°25'22"E., 1,859.35 ft. dist., monumented with an iron post, 1 in. diam., 12 ins. above ground, firmly set, with a brass cap properly mkd.		
	A cairn, 2 x 3 ft. base, 3 ft. high, bears S.70°W., 4 ft. dist.		
	No local bearing objects or bearing trees available.		
	Thence S.10°01'38"E.		
65.	Power line, bears N.16°30'W. and S.16°30'E.		
220.	Power line, bears N.64°E. and S.64°W.		
235.	Buried telephone cable, bears N.20°E. and S.20°W.		
330.00	Cor. No. 2, identical with Cor. No. 1 of the Harborlite Millsite No. 2 of this survey and center of unimproved dirt road, 30 ft. wide, bears N.21°E. and S.21°W.		
	This corner falls in the center of a road where a permanent monument cannot be established; from which		
	The point for witness corner bears S.10°01' 38"E., 173.78 ft. dist.		
	Thence S.79°58'22"W.		
55.	Buried telephone cable, bears N.20°E. and S.20°W.		
180.	Power line, bears N.22°E. and S.22°W.		
345.	Power line, bears N.63°30'E. and S.63°30'W.		
435.	Power line, bears N.21°30'W. and S.21°30'E.		
660.00	Cor. No. 3, identical with Cor. No. 4 of the Harborlite Millsite No. 2 of this survey.		
	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X H. M.S. 1 3 H. M.S. 2 4 U.S.M.S. 4845; from which		

1)				
FEET	A wood post, 2 x 2 ins. in size, 4 ft. above ground, in a cairn, bears S.50°E. 2 ft. dist.			
	No local bearing objects or bearing trees available.			
	Thence N.10°01'38"W.			
330.00	Cor. No. 4.			
	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X H. M.S. 1 4 U.S.M.S. 4845; from which			
	A cairn, 3 ft. base, 3 ft. high, bears S.20°E., 5 ft. dist.			
	No local bearing objects or bearing trees available.			
	Thence N.79°58'22"E.			
160.	Power line, bears N.21°30'W. and S.21°30'E.			
382.	Railroad track, bears N.64°W. and S.64°E.			
651.	Power line, bears N.16°30'W. and S.16°30'E.			
660.00	Cor. No. 1, and place of beginning.			
¥	The Harborlite Millsite No. 1 contains 5 acres.			
:	HARBORLITE MILLSITE NO. 2			
	Beginning at Cor. No. 1 of the Harborlite Mill- site No. 2, identical with Cor. No. 2 of the Harborlite Millsite No. 1.			
	This corner falls in the center of a road where a permanent monument cannot be established; from which			
	The S. 1/4 sec. cor. of sec. 34 bears N.29° 53'03"E., 2,100.38 ft. dist., heretofore described.			
	Thence S.10°01'38"E.			
173.78	Point for witness Cor. No. 1, identical with the witness cor. for Cor. No. 2 of the Harborlite Millsite No. 1 of this survey.			
-	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X W.C. H. M.S. 1 2 H. M.S. 2 1 U.S.M.S. 4845; from which			
	A cairn, 2 ft. base, 2 1/2 ft. high, bears N.30°E., 1 1/2 ft. dist.			
	No local bearing objects or bearing trees available.			

Mineral Survey No. 4845

_{РЕЕТ} 225.	Buried gas pipeline, bears N.8°E. and S.8°W.		
330.00	Cor. No. 2.		
	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X H. M.S. 2 2 U.S.M.S. 4845; from which		
	A wood post, 2 x 2 ins. in size, 4 ft. above ground, in a cairn, bears N.63°W., 2 ft. dist.		
	No local bearing objects or bearing trees avail- able.		
	Thence S.79°58'22"W.		
36.	Buried gas pipeline, bears N.8°E. and S.8°W.		
195.	Center of unimproved dirt road, 22 ft. wide, bears N.21°E. and S.21°W.		
245.	Buried telephone cable, bears N.20°E. and S.20°W.		
660.00	Cor. No. 3.		
	Set an iron post, 30 ins. long, 3/4 in. diam., 18 ins. in the ground, in a concrete and rock base, with a brass cap firmly secured to the iron post, mkd. X H. M.S. 2 3 U.S.M.S. 4845; from which		
	A wood post, 2 x 2 ins. in size, 4 ft. above ground, in a cairn, bears S.49°E., 2 1/2 ft. dist.		
	No local bearing objects or bearing trees available.		
	Thence N.10°01'38"W.		
230.	Power line, bears N.63°30'E. and S.63°30'W.		
330.00	Cor. No. 4, identical with Cor. No. 3 of the Harborlite Millsite No. 1 of this survey.		
	Thence N.79°58'22"E.		
225.	Power line, bears N.21°30'W. and S.21°30'E.		
315.	Power line, bears N.63°30'E. and S.63°30'W.		
480.	Power line, bears N.22°E. and S.22°W.		
605.	Buried telephone cable, bears N.20°E. and S.20°W.		
660.00	Cor. No. 1, and place of beginning.		
	The Harborlite Millsite No. 2 contains 5 acres.		

·•/	
FEET	AREAS Acres
	Total area, Harborlite Millsite No. 1 5.000
	Total area, Harborlite Millsite No. 2 5.000
	LOCATION
	This survey is located in the NW 1/4 sec. 4, T.2 S., R.12 E., G.& S.R.M. The survey of the Harborlite Millsite Nos. 1 and 2 is identical with the location as marked on the ground.
	EXPENDITURES
	None
	OTHER IMPROVEMENTS
	A steel frame and corrugated sheet steel mill building for processing perlite ore - storage tanks, crushers, conveyors, etc. The NW cor. of the building bears S.19°W., 180 ft. from Cor. No. 1 Harborlite Millsite No. 1; 40 x 60 ft. in size, the long sides bear S.64°E. Claimant herein
	A steel ore hopper, the NW cor. of which bears S.4°W., 172 ft. from Cor. No. 1 Harborlite Millsite No. 1; 10 x 12 ft. in size, the long sides bear S.26°W. Claimant herein
	A frame mobile home trailer, the NE cor. of which bears S.53°W., 168 ft. from Cor. No. 1 Harborlite Millsite No. 2; 8 x 42 ft. in size, the long sides bear S.25°W. Claimant herein
8	A frame mobile home trailer, the NE cor. of which bears S.42°30'W., 260 ft. from Cor. 10. 1 Harborlite Millsite No. 2; 12 x 57 ft. in size, the long sides bear S.25°W. Claimant herein
	A standard guage railroad spur track for serv- icing the perlite mill. Claimant unknown.
	Power lines for servicing the perlite mill and mobile home trailers. Claimant unknown
j	A buried telephone cable. Claimant unknown
	A buried gas pipeline. Claimant unknown

OTHER CORNER DESCRIPTIONS AND SUPPLEMENTAL DATA			NS
	1	None	
	N	1EMORANDUM	
		None	=
	FIELD ASSISTANTS		
ii ii	Name		Capacity
	Kent Miller	Assistant	Instrumentman
	Joe Nachtigall	R	odman-Chainman
. U			
	2 ×1		

Form 3860-7 (November 1976) (formerly 3400-8)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CERTIFICATE OF SURVEYOR

Name of Mineral Surveyor		Date			
Harvey W. Smith		December 23, 1981			
I HEREBY CERTIFY That in pursuance of an ord	der received from the Bure , at Phoenix, A				
dated November 30, , of Harborlite Corporation	19 81 , I have carefully o	executed the survey of the claim			
known as the (lode, placer, or mill site) Harbor	lite Millsite Nos. 1	and 2			
situated in Section 4		, Township 2 S. ,			
Range 12 E., Gila & Salt River	Meridian, in the State of	Arizona .			
This survey, designated as number 4845 been made in strict conformity with said order, the United States, and in specific manner describes	e Manual of Instructions fo				
I FURTHER CERTIFY That the labor expended (lode or placer)	and improvements made	upon and for the benefit of the location(s)			
embraced in the said mining claim by claimant(s)	or				
grantors are fully stated in my report. The chara- full detail. No portion of, or interest in, said lab cluded in the estimate of expenditures upon any of	or and improvements so cre				
		July -			
Scottsdale, Ariz ona	- BHULL	MARIE			
(Location)	(Signatur	e of Mineral Surveyor)			
The state of the s					
CERTIFICA	ATE OF APPROVAL				
		Office			
		Arizona State Office			
		Location Phoenix, Arizona			
		Date			
		October 1, 1985			
The foregoing field notes of mineral survey numb	er 4845 in the	NW 4 of section 4			
	, X surveyed un				
Range 4 E., Gila and Salt River N	leridian, in the State of	Arizona ,			
executed by Harvey W. Smith		, Mineral Surveyor,			
		ally examined and the necessary			
corrections made prior to their certification by the	e surveyor, the field notes	and the survey therein described			
are hereby approved.					
1. SACN SL					
funda E. Might	Acting Chief Cad	lastral Surveyor of Arizona			
(Authorized Agnature)		(Title)			
CEDTICIOA	TE OF TRANSCOIRT				
CERTIFICA	HE OF TRANSCRIPT				
I HEREBY CERTIFY That the foregoing transcript of field notes of the above-described mineral survey number 4845 is a true copy of the original field notes.					
	A				
	Acting Chief Cad	lastral Surveyor of Arizona			
(Authorized Signature)		(Title)			

to contact the second s

So wardered Linker of Told Introl

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT ARIZONA STATE OFFICE

9605 (942) M.S. 4845

NOTICE OF CANCELLATION OF MINERAL SURVEY

The Harborlite Millsite No. 1 and Harborlite Millsite No. Mineral Survey No. 4845, located in Township 2 South, Range 12 East, Gila and Salt River Meridian, Arizona, are hereby canceled. As of this date, this notice of cancellation will become part of the field notes for Mineral Survey No. 4845, page 13.

These claims have not been filed with the Arizona State Office, Bureau of Land Management, in accordance with Section 314, 90 STAT. 2769, (43 U.S.C. 1744).

This cancellation was necessitated to clear the record.

The Mineral Survey Plat will be noted as follows:

"Harborlite Millsite No. 1 and Harborlite Millsite No. 2, Mineral Survey No. 4845 were canceled February 28, 1994, by memo 9605 (942) M.S. 4845, which is now a part of the original field notes."

February 28, 1994

Date

Chief Cadastral Surveyor of Arizona

James P. Lelley

BUREAU OF LAMP MANAGEMENT

Harborlite Millaire Ma 1 and Harberlik stiftodiek Mineral Survey No. 4845, located in Township 2 South, Rander East, the and Salt Elect Meridian, arizons, are hereby cancalto of this date, this notice of canceristion will become part the field notes for Mineral Survey No. 4845, page 11.

These claims have not been filed with the Arizona Stars (if c